


# MODEL PDS DIMENSIONS



	<b>2 Tons</b>	<b>3 Tons</b>	<b>4 Tons</b>	<b>6 Tons</b>
<b>PRT #</b>	<b>PDS-2.0-A</b>	<b>PDS-3.0-A</b>	<b>PDS-4.0-A</b>	<b>PDS-6.0-A</b>
<b>A</b>	0 - 1 5/8"	0 - 1 5/8"	0 - 2 1/8"	0 - 2 1/8"
<b>B</b>	4 3/4"	4 3/4"	5 3/8"	5 3/8"
<b>C</b>	9 1/2"	9 1/2"	12 1/4"	12 1/4"
<b>D MAX</b>	15 1/4"	15 1/4"	19"	19"
<b>E</b>	3"	3"	3 1/2"	3 1/2"
<b>F</b>	9 1/8"	9 1/8"	11 1/8"	11 1/8"
<b>G</b>	3 7/8"	3 7/8"	4 3/4"	4 3/4"
<b>H</b>	3"	3"	3"	3"
<b>J</b>	3/4"	3/4"	1"	1"
<b>K</b>	5/8"	5/8"	3/4"	3/4"
<b>L</b>	4 1/8"	4 1/8"	5 1/8"	5 1/8"
<b>WT</b>	32 lbs.	34 lbs.	55 lbs.	57 lbs.